



INSPECTION REPORT

MY STELLA MARIS

21073

BodhiNautic team was requested to repair the Slide of MY Stella Maris.

The purpose of this report is to show the defects found during the slide's inspection, and explain the reparation solution proposed.

The slide doesn't present air leaks, we have controlled the air pressure during 48h and it was fine.



PVC strip totally detached approximately 180cm from main tube.



Additional 220cm partially detached. The proposed reparation solution is to reglue the opened areas and reinforce with additional strip 4-5cm width along a total length 500cm up to the end on the top side.



Refit D-Ring ripped off on the top part of the slide and reinforce the area with new PVC material same colour.



Reglue 3 lifting eyes patches coming off on side main section tube and reinforce the area with new PVC material same colour.



Reparation of small peelings on PVC patches & accessories, included on the pressure test and inspection service.





